# Oil Field Environmental Incident Summary

Responsible Party: Schiele Trucking

Well Operator: BUCKHORN ENERGY SERVICES, LLC

Well Name: VINGER 1

Field Name: WHEELOCK Well File #: 90212

Date Incident: 7/23/2014 Time Incident: 19:00 Facility ID Number:

County: WILLIAMS Twp: 156 Rng: 98 Sec: 21 Qtr: SE SE

Location Description:

Submitted By: Nancy Roberts Received By:

Contact Person: Joe Schroeder

PO BOX 630530

LITTLETON, CO 80163

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 15 Barrels 14 Barrels 14 barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/13/2017 Clean Up Concluded: 7/24/2014

Risk Evaluation:

None

Areal Extent:

## Potential Environmental Impacts:

Only soil actually on the site was impacted. All fluid was immediately picked up by vac truck.

### Action Taken or Planned:

All fluid was immediately picked up by vac truck.

Wastes Disposal Location: Fluid recovered was disposed of at the Vinger SWD.

Agencies Involved:

#### **Updates**

Date: 7/25/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. NDIC retains oversight.